

Harness inspection certificate - EN / NfL

Inspection certificate number: PH_497.2026

Impact pad number: n/a

Manufacturer data

Manufacturer name: **Woody Valley srl**
Representative: **Simone Caldana**
Street: **Via Linz 23**
Post code / place: **38121 Trento**
Country: **Italy**

Sample data:

Harness

Impact pad

Name:	Wani 4	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	Yes
Size:	M	Impact pad type:	Airbag
Weight of Sample [kg]:	4.1	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	122 0115 001P	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120		
Integrated container for rescue system:	No	Date of reception:	n/a
Volume container [cm ³]:	max 3000 min 5600		
Date of reception:	19.12.2025		

Test report summary

Structual test

Impact pad test

RDT / RST

Result:	POSITIVE	POSITIVE	POSITIVE
Remark:			
Place:	Villeneuve	Villeneuve	Villeneuve
Date:	19.12.2025	19.12.2025	19.12.2025

Issue data

Place of declaration: **Villeneuve**
Date of issue: **01.01.2026**
Managing Director: **Andrea Wigger**
Signature: 

This signature approve the validity of the test reports 94.21a and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

EN1651:2018+A1:2020 and EN12491:2015+A1:2021 and NfL 2024-2-785

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag

The certificate of inspection is completed with test reports, if available, number: 94.21a and 94.22

The declaration must not be reproduced in part without the written permission of Air Turquoise SA